

To: Susan Hakanson[Susan.Hakanson@co.laplata.co.us]; Sarah Jacobson[Sarah.Jacobson@co.laplata.co.us]; Joanne Spina[Joanne.Spina@co.laplata.co.us]; Joe Kerby[Joe.Kerby@co.laplata.co.us]; Sean Smith[Sean.Smith@co.laplata.co.us]; Frank Sandoval[Frank.Sandoval@co.laplata.co.us]; Edward Aber[Edward.Aber@co.laplata.co.us]; Todd Hitti[Todd.Hitti@co.laplata.co.us]; Butch Knowlton[Butch.Knowlton@co.laplata.co.us]; Tom McNamara[tommymoto@gmail.com]; Faulk, Libby[Faulk.Libby@epa.gov]

From: Daniel Bender

Sent: Mon 8/10/2015 12:06:08 AM

Subject: Catch basins operating

[IMG_0384.JPG](#)

[ATT00001.txt](#)

[IMG_0373.JPG](#)

[ATT00002.txt](#)

[IMG_0371.JPG](#)

[ATT00003.txt](#)

[IMG_0368.JPG](#)

[ATT00004.txt](#)

Attached are catch basins just above Cement Creek. I sent photos to some of you Saturday showing them in final stages of readiness. There are additional basins at the mine portal. Also attached is Cement Creek running thru a culvert at the intersection of SJC Rds 110 & 10. Significantly clearer than photos I took at the same location Saturday Dan Bender, LPCSO